



September 2020

## Oil Coalescing Air Dryer Cartridges.

With the introduction of EPA 07 and EPA 10 emission standards, the responsibility to protect these new vehicle technologies falls directly on the equipment owner. Now, more than ever before, Air Dryers with oil coalescing technology are critical to preserving your vehicle systems and keeping you on the road.

In the past, you didn't need to think much about your air dryer. You could get by with "if it isn't broke, don't mess with it". Those Days are now gone!

With the addition of expensive Engine After Treatment Systems (EATS), clean moisture free and oil free air is important to the operation and life of these new systems. Non Coalescing cartridges are the same size as coalescing cartridges. This is true for both Wabco and Bendix air dryer cartridges. The difference in these coalescing cartridges is that a coalescing cartridge will trap oil that could enter your truck's air system. Without the oil coalescing features of these cartridges, oil can contaminate expensive components and could lead to costly repairs and down time.

Part Number Reference WX 4329012482 R950068A

See reverse side for Bendix Oil Coalescing Cartridges.



Contact your local Sales Representative to find out more about these products.







Page 2 of 2

## Bendix' PuraGuard' Oil Coalescing Cartridge Application Guide

Air dryer cartridge part numbers shown in blue provide the increased performance of Bendix® PuraGuard® oil coalescing technology

	Air Dryer		Vehicle Year	
Vehicle Make			Pre-2004 2004 - 2006	2007 - 2009   2010 & news
			Emission Standard	
			Pre-EPA '04 EPA '04	EPA '07 EPA '10
Volvo/Mack	AD-9®	Service New	<b>107796PG</b> , 107796	107796PG
		Reman	<b>107794PG</b> , 107794	107794PG
	AD-IP®	Service New	<b>065624PG</b> , 065624	065624PG
		Reman	<b>109493PG</b> , 109493	109493PG
	AD-IS®	Service New	<b>5008414PG</b> , 5008414	5008414PG
	NOTE: PuraGuard® Coalescing Cartridges required for all models beginning in 2008 model year.			
Freightliner & Western Star	AD-9®	Service New	107796PG,	107796
		Reman	107794PG,	107794
	AD-IP®	Service New	065624PG,	065624
		Reman	109493PG,	109493
	DRM™ / AD-IS®	Service New	5008414PG	, 5008414
	NOTE: PuraGuard® Coalescing Cartridges required for all vehicles equipped with Detroit Diesel DD-13® and DD-15™ engines, beginning in 2010 model year.			
			· · · · · · · · · · · · · · · · · ·	in Ed to model year.
Kenworth & Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow®	Service New	5008414PG	-
	AD-IS® AD-SP® AD-IS® EverFlow®			, 5008414
	AD-IS® AD-SP®	Service New	5008414PG	, 5008414 107796
	AD-IS® AD-SP® AD-IS® EverFlow®	Service New	5008414PG, 107796PG,	, 5008414 107796 107794
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow® AD-9®	Service New Service New Reman	5008414PG, 107796PG, 107794PG,	, 5008414 107796 107794 065624
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow® AD-9® AD-IP® / AD-IP® EverFlow®	Service New Service New Reman Service New	5008414PG, 107796PG, 107794PG, 065624PG,	, 5008414 107796 107794 065624 109493
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow® AD-9®	Service New Service New Reman Service New Reman	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG,	, 5008414 107796 107794 065624 109493 065624
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow® AD-9® AD-IP® / AD-IP® EverFlow®	Service New Service New Reman Service New Reman Service New	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG, 065624PG,	107796 107794 065624 109493 065624 109493
	AD-IS® AD-SP® AD-IS® EverFlow®  AD-9®  AD-IP® / AD-IP® EverFlow®  AD-IP®  AD-IS®	Service New  Service New  Reman  Service New  Reman  Service New  Reman	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG, 065624PG, 109493PG,	, 5008414 107796 107794 065624 109493 065624 109493 5008414
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow®  AD-IS® EverFlow®  AD-IP® / AD-IP® EverFlow®  AD-IP®	Service New  Service New  Reman  Service New  Reman  Service New  Reman  Service New	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG, 065624PG, 109493PG, 5008414PG,	107796 107794 065624 109493 065624 109493 5008414
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow®  AD-IS® EverFlow®  AD-IP® / AD-IP® EverFlow®  AD-IP®  AD-IS®  AD-9® / AD-9® EP /	Service New Reman Service New Reman Service New Reman Service New Reman Service New Service New	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG, 065624PG, 109493PG, 5008414PG, 107796PG,	107796 107794 065624 109493 065624 109493 5008414 107796
Peterbilt	AD-IS® AD-SP® AD-IS® EverFlow®  AD-IS® EverFlow®  AD-IP® / AD-IP® EverFlow®  AD-IP®  AD-IS®  AD-9® / AD-9® EP / AD-9® EverFlow®	Service New Reman	5008414PG, 107796PG, 107794PG, 065624PG, 109493PG, 065624PG, 109493PG, 109794PG,	107796 107794 065624 109493 065624 109493 5008414 107796 107794